



TECHNICAL TIDBITS



MATERION PERFORMANCE ALLOYS

A BETTER RATE: FLOW STRESS, STRAIN RATE & STRAIN RATE SENSITIVITY

Go with the Flow!

– How changes in speed affect the way that materials and environmental forces interact.

- ▲ Strain Hardening
- ▲ Non-Uniform Elongation
- ▲ Strain Hardening Coefficient (K)
- ▲ Strain Hardening Exponent (n)
- ▲ Flow Stress
- ▲ Strain Rate Sensitivity
- ▲ Strain Rate Sensitivity Exponent / Strain Rate Hardening Exponent (m)
- ▲ Slow Strain Rate Tensile Testing

Recall the results of a tensile test are plotted as stress-strain curves, as shown in Figure 1. The engineering stress-strain curve rises linearly to the point of plastic deformation then increases more slowly as the material **strain hardens** until it reaches the ultimate

tensile strength. Then it starts to fall off as the sample begins to neck down in thickness. (This elongation after necking is called **non-uniform elongation**.) The true stress-strain curve rises continuously to the point of fracture.




Figure 1. Engineering and True Stress-Strain Curves.

Once strain hardening begins, the true stress-strain curve is always higher than the engineering stress-strain curve, since the instantaneous cross section after yielding is always smaller than the original cross section.

Furthermore, if you plot the true-stress-strain curve on log-log coordinates, you can generate a numerical expression for the strain hardening, as shown in Figure 2. The coefficients are the **strain hardening coefficient (K)** and the **strain hardening exponent (n)**. This exponent is a measure of how the stress changes with the instantaneous strain.

During plastic deformation, the stress level that is required to keep the deformation continuing is called the **flow stress**. This property is typically measured in a compression test, unlike most other properties associated with strain hardening, which are measured in tension. The sample usually is cylindrical with an aspect ratio of 3:2, as shown in Figure 3. Multiple flow stress tests are typically run on a material to quantify deformability of the material, usually at different strain rates and at different temperatures.




Figure 2. Strain Hardening Behavior of a High Strength Copper Alloy. Note that the linear fit of the plastic strain region on the log-log scale is very good, so that it is easy to calculate the strain hardening coefficient and exponent. However, the fit in the elastic region and in the knee of the curve is not so good. This is why the full true stress-strain curve or even a bilinear approximation of it is preferred for Finite Element Analysis.

The next issue of Technical Tidbits will discuss electrical and thermal conductivity.

A BETTER RATE: FLOW STRESS, STRAIN RATE & STRAIN RATE SENSITIVITY (CONTINUED)

In this case, the results of the flow stress test illustrate that the peak stress is higher as the strain increases. If the material shows different behaviors at different strain rates, it is said to have strain rate sensitivity. Like the strain rate exponent (n) governs the slope of the stress-strain curve at a given strain,

$$\text{Strain Hardening Exponent (n)} = \frac{\partial \sigma}{\partial \epsilon} = \frac{\log(\sigma_2/\sigma_1)}{\log(\epsilon_2/\epsilon_1)}$$

the strain rate sensitivity exponent (m), also known as the strain rate hardening exponent, governs the slope of the stress-strain-curve at a given strain rate. The astute reader will note that this means that the exponent is a function of strain rate, and is therefore not a constant, unless m=0.

$$\text{Strain Rate Sensitivity Exponent (m)} = \frac{\partial \sigma}{\partial \dot{\epsilon}} = \frac{\log(\sigma_2/\sigma_1)}{\log(\dot{\epsilon}_2/\dot{\epsilon}_1)}$$




Figure 3. Compressive flow stress curve of a copper alloy (left) and representative samples, before and after testing (right).

Note that as the strain rate increases, it takes a higher amount of flow stress to continue deforming the material. This means that the material effectively has a higher strength when the deformation is faster.

The strain rate sensitivity exponent governs how a material deforms. If the exponent is positive, then, tensile properties such as yield strength, tensile strength, percent elongation, and reduction of area increase as strain rate increases. The material can better spread the deformation associated with necking, leading to greater non-uniform elongation and improved formability. Since all these effects result in more area under the stress strain curve, toughness improves as well. A negative exponent will result in forming difficulties, as the material will be unable to spread the non-uniform deformation, and failure will begin immediately at the point of necking.

As an aside, in **slow strain rate testing (SSRT)**, a tensile sample is pulled to failure at a very low strain rate in an environment known to promote stress corrosion cracking or hydrogen embrittlement in the particular material tested. The slow strain rate is not chosen for its effect on the mechanical properties of the material, but rather for its tendency to encourage stress corrosion cracking of the material in the test environment. Nevertheless, the measured ductility of the specimens at failure is usually directly proportional to the strain rate.

Written by Mike Gedeon of Materion Performance Alloys Marketing Department. Mr. Gedeon's primary focus is on electronic strip for the automotive, telecom, and computer markets with emphasis on application development.

References:

Keeler, Stuart "Strain-Rate Hardening: Small Number, Big Impact" MetalForming Magazine June 2014

Keeler, Stuart "Stress-Strain Curves Give Visual Clues about Formability" MetalForming Magazine July 2015

Smith, J.E. "Tension Tests of Metals at strain rates up to 200 sec⁻¹" Materials Research and Standards, Vol. 3 (September 1963), pp. 713-718

Deiter, G. E.; Kunh, H. A. & Semiatin, S. L. Handbook of Workability and Process Design ©2003 ASM International

Dieter, George E. Jr. Mechanical Metallurgy ©1961 McGraw-Hill Book Company, Inc.

"Technical Tidbits" Issues 14, 17, 45, 46, 50 and 51

ASM Handbook Vol. 13A Corrosion: Fundamentals, Testing, and Protection. © 2003 ASM International

Please contact your local sales representative for further information on material hardness or other questions pertaining to Materion or our products.

Health and Safety

Handling copper beryllium in solid form poses no special health risk. Like many industrial materials, beryllium-containing materials may pose a health risk if recommended safe handling practices are not followed. Inhalation of airborne beryllium may cause a serious lung disorder in susceptible individuals. The Occupational Safety and Health Administration (OSHA) has set mandatory limits on occupational respiratory exposures. Read and follow the guidance in the Material Safety Data Sheet (MSDS) before working with this material. For additional information on safe handling practices or technical data on copper beryllium, contact Materion Performance Alloys or your local representative.



TECHNICAL TIDBITS

Materion Performance Alloys
6070 Parkland Blvd.
Mayfield Heights, OH 44124

Sales
+1.216.383.6800
800.321.2076
BrushAlloys@Materion.com

Technical Service
+1.216.692.3108
800.375.4205
BrushAlloys-Info@Materion.com

